

SEATS and BENCHES- JULY 2017

Location		Plaque(s)		Condition	Action
1.	Main Street (outside Main Street Community Church)	2	Cllr G E Bushell & Cllr J Berry	Metal ends- wooden slats; slight deterioration of wood stain on slats	LOW
2.		2	Cllrs M Roche & D Thompson	Metal ends- wooden slats; slight deterioration of wood stain on slats	LOW
3.	Junction of Main Street & Marsh Lane	2	Cllrs W Ellams & A Hughes	Metal ends- wooden slats; slight deterioration of wood stain on slats	LOW
4.		2	Cllrs S Atherton & C Pritchard	Metal ends- wooden slats; slight deterioration of wood stain on slats	LOW
5.	High Street (outside St Luke's Church)	0		Metal ends- wooden slats; slight deterioration of wood stain on front edge	LOW
6.	Junction of A56 & St Hilda's Drive	1	Cllr D Close	Metal ends- wooden slats; slight deterioration of wood stain on slats	LOW
7.		0		Metal ends- wooden slats; slight deterioration of wood stain on slats	LOW
8.	Junction of A56 & Howey Lane	1	Cllr S Williams	Metal legs- wooden slats; deterioration of wood stain on slats	MED
9.	Bridge Lane (North side) – The Quay	0		Concrete legs- wooden slats; major deterioration of wood stain on slats	HIGH
10.	Bridge Lane (South side)	0		Metal legs- wooden slats; deterioration of wood stain on slats	MED
11.	Church Street (Railway Bridge)	1	Cllr C Doughty	Bench removed- awaiting replacement	-
12.	Churchfields Play Area 3 new benches added in 2015	1	Cllr R Astbury	Metal legs- wooden slats; major deterioration of wood stain on slats	HIGH
13.		1	Cllr E Lakin	Metal legs- wooden slats; major deterioration of wood stain on slats	HIGH
14.		1	Cllr F R Harrison	Metal legs- wooden slats; major deterioration of wood stain on slats	HIGH
15.		0		Metal- painted black	NO ACTION
16.		0		Metal- painted black	NO ACTION

LOW- monitor, no action at present

MED- routine painting to be programmed

HIGH- no protection, requires painting

SEATS and BENCHES- JULY 2017

17.		0		Metal- painted black	NO ACTION
18.	Junction of Red Lane & Churchfields	1	Cllr A Jones	Metal legs- wooden slats; major deterioration of wood stain on slats	HIGH
19.	Junction of Church Street & London Rd	0		Metal legs- wooden slats; deterioration of wood stain on slats	MED
20.	Junction of Red lane & Townfield Lane	1	Cllr H Tudor	Metal legs- wooden slats; major deterioration of wood stain on slats	HIGH
21.	Junction of Red lane & Bradley Lane	0		Replaced bench with plastic one	NO ACTION
22	Red Lane/Vicarage Lane	1	Cllr F J Cox	Metal legs- wooden slats; major deterioration of wood stain	HIGH
23	Townfield Lane Play Area	1	Cllr J Fidler	Metal legs- wooden slats; major deterioration of wood stain	HIGH
24		0		Metal legs- wooden slats; major deterioration of wood stain	HIGH
25	Blue Hatch	0		Metal legs- wooden slats; deterioration of wood stain	MED
26	Ship Street Community Orchard – picnic bench	0		Plastic	NO ACTION
27	Junction of Bellemonte Road & Penkmans Lane	1		Metal legs- wooden slats; slight deterioration of wood stain	LOW
28	Bellemonte Road (Memorial Gates)	1	Cllr V J Edgar	Metal legs- wooden slats; slight deterioration of wood stain	LOW
29		0		Metal bench	NO ACTION
30	Marshlands	0		Metal bench	NO ACTION
31	Memorial Field WW1 Commemorative Bench added in 2016	1	Mr C G Baker	Metal legs- wooden slats; deterioration of wood stain on slats	MED
32		1	Mr M R Kimber	Metal legs and back- wooden slats; slight deterioration of wood stain	LOW
33		1	Mr & Mrs Ormsby	Plastic bench	NO ACTION

LOW- monitor, no action at present

MED- routine painting to be programmed

HIGH- no protection, requires painting

SEATS and BENCHES- JULY 2017

34	Commemorative bench	1	Mr & Mrs Yates	Metal bench- black paint requires touching up	LOW
35		1	Cllr H Pyle	Metal legs- wooden slats; major deterioration of wood stain	HIGH
36		0		Metal bench	NO ACTION
37		0		Metal bench	NO ACTION
38	Junction of Ship Street & Hayes Crescent	2	Cllr E Andrews & Cllr P Cooney	Metal legs- wooden slats; one wooden slat missing; major deterioration of wood stain on the rest	HIGH
39	Junction of Kingsley Road & Top Road	1	Cllr T G Williams	Metal legs- wooden slats; deterioration of wood stain on some slats	MED
40	Top Road	1	Cllr I Riley	Metal legs- wooden slats; deterioration of wood stain on slats	MED
41	Churchfields Road – between Cobal Court & St Lawrence Rd	0		Concrete legs- wooden slats; major deterioration of wood stain	HIGH

LOW- monitor, no action at present

MED- routine painting to be programmed

HIGH- no protection, requires painting