

## Grounds inspections summary - February 2023

### Churchfields

- Damage to wooden fencing. Part of wooden handrail missing.
- Damage to safety surface.
- Wooden bridge slippery due to poor weather. Recommend the pathway be jet washed to remove slip hazard.
- Part of wooden wall missing.

### Park Lane

- Remove graffiti off bench
- Treat moss on paths

### Cemetery

- Toilet light needs fixing
- Top up grave in new section
- Ship Street
- Missing bin lid

### Memorial

- Car park bench needs painting/replacing



- Needs additional bins
- Needs additional bench along pathway

### Churchfields allotments

- Clear rubbish at the back of the fence line
- Weed and treat moss on pathways

### Top Road

- Install replacement bench
- Ashton Drive allotments
- Some plots are not being tended properly
- Townfield Lane
- Top up under 1 bay swing