

Churchfields Inspection Sheet



Northwich
town council

Inspection Start: 5 January 2022 at 12:49

Inspected By: Charlie

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Gates	No Hazard	—	—
Signs	Needs Replacing	—	Replace
One sign bent needs replacing			
Bins	No Hazard	—	Remove
Not emptied again.			
Benches	Needs Replacing	—	Repair
Bench broken and bent needs removing or repairing			
Supernova	Needs Replacing	Low	Repair
Matting underneath needs replacing			
Pendulum swing	No Hazard	—	—
Seesaw	No Hazard	—	—
Flat Swings	No Hazard	—	—

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Cradle swings	No Hazard	—	—
One swing missing.			
Embankment slide	No Hazard	None	None
		—	
Steps	No Hazard	—	—
		—	
Embankment slide2	No Hazard	—	—
Bridge	No Hazard	—	Repair
Wood missing in areas of bridge		—	
Wooden wall	No Hazard	None	None
		—	
Blue frame swings	No Hazard	—	—
Rubber starting to split.			
Bike springer	Missing Parts	—	—
One handle missing. Front wheel wood chipped			
Tractor springer	No Hazard	—	—
Could do with a clean and painting.			

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Goal post	Needs Replacing	Medium	Repair

Goal mouths needs topping with soil , one goal leaning over been pulled

Safety Surfacing	No Hazard	—	—
------------------	-----------	---	---

Bit missing under wooden bridge.

Comments:

Grass and weeds growing around stone steps, wooden steps and embankment slides. Embankment could do with strimming.

Bins not been emptied

Bench broken and bent needs removing

Wood missing in areas of bridge

Lamp post cover needs fixing

Safety matting needs replacing under bridge

Photo 1:



Photo 2:



Photo 4:



Photo 5:



Photo 7:



Photo 8:



Photo 9:



Photo 10:





Immediate Action:

None

Inspection
Completed:

5 January 2022 at 13:23

Signature:

CAWPC

Addition
comments:

Location:

