

Churchfields Inspection Sheet



Northwich
town council

Inspection Start:

Inspected By:

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Gates	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Signs	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Bins	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Benches	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Supernova	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Pendulum swing	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Seesaw	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Flat Swings	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Cradle swings	No Hazard	—	—
Embankment slide	No Hazard	—	—
		—	
Steps	No Hazard	—	—
		—	
Embankment slide2	No Hazard	—	—
Bridge	No Hazard	—	—
		—	
Wooden wall	No Hazard	—	—
		—	
Blue frame swings	Missing Parts	—	—
2 swings missing			
Bike springer	No Hazard	—	—
Tractor springer	No Hazard	—	—

Equipment

Hazard

Risk H/M/L

Recommended Action/s

Goal post

No Hazard

—

—

Safety Surfacing

Needs Repairing

—

—

Weed growing in areas, some bits missing.

Comments:

Photo 1:



Photo 2:



Photo 3:



Photo 4:





Authorised By:

Ian

Immediate Action:

None

Inspection
Completed:

4 April 2023 at 10:42

Signature:

Addition
comments:

Branches need removing.

Location:



Marl Pits Inspection Sheet



Inspection Start: 14 March 2023 at 15:36

Inspected By: Steph

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Paths	—	Low	Remove
Entrance needs cutting back could with some Bark or something putting down on it very muddy in			
Trees (Visual)	—	Low	Monitor
Some tree roots sticking out of ground in areas			
Fence	No Hazard	—	—
Grass Areas	No Hazard	—	—
Benches	No Hazard	—	—
Plants	No Hazard	—	—
Bins	No Hazard	—	—

Comments:

Entrance needs cutting back roots sticking out of paths trip hazards

Paths ways very muddy and slippery due too weather conditions

Photo 1:





Immediate Action:

None

Inspection
Completed:


8 December 2020 at 09:17

Signature:

Chloe

Addition
comments:

Location:



Marshlands Inspection Sheet



Inspection Start: 14 March 2023 at 14:05

Inspected By: Steph

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Paths	No Hazard	—	None
Could do with a clean up			
Trees (Visual)	Needs Replacing	Medium	Remove
Some want cutting back			
Fence	No Hazard	—	None
Grass Areas	No Hazard	—	—
Benches	Safety Fencing Damaged	—	—
Plants	No Hazard	—	—
Bins	No Hazard	—	—
Area is desperate for a bin around bench area			

Comments:

Area desperately in need of a bin near bench area

Litter pick

Could do with a hedge cut back around it



Immediate Action:

None

Inspection
Completed:


17 May 2022 at 13:26

Signature:

CAW JF

Addition
comments:

Location:



Park Lane Park Inspection Sheet



Inspection Start:

Inspected By:

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Paths	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Surface	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Signs	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Gates	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Fence	<input type="text" value="Needs Adjusting"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text" value="Bent in one area"/>			
Seating	<input type="text" value="Needs Cleaning"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text" value="Graffiti on bench"/>			
Bin	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Wall	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Cradle swing	No Hazard	-	-
Flat swing	-	-	-
Inclusive swing	No Hazard	-	-
Roundabout	No Hazard	-	-
Toddler multiplay	No Hazard	-	-
Bee springer	Needs Cleaning	-	-
Graffiti on seat			
Seesaw	Needs Cleaning	-	-
Graffiti on seat			
Outdoor gym	No Hazard	-	-

Comments :

Photo 1:



Photo 2:



Photo 3:



Photo 4:



Photo 5:



Photo 6:





Authorised By:

Ian

Immediate Action:

None


Inspection
Completed:

4 April 2023 at 11:04

Signature:

Addition
comments:

Location:



Top Road Park Inspection Sheet



Inspection Start:

Inspected By:

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Paths	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Surface	<input type="text" value="Needs Cleaning"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text" value="Bird muck on surface"/>			
Signs	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Gates	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Fence	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Seating	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Bin	<input type="text" value="No Hazard"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text"/>			
Flat swing	<input type="text" value="Needs Cleaning"/>	<input type="text" value="—"/>	<input type="text" value="—"/>
<input type="text" value="Bird muck"/>			

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Cradle swing	Needs Cleaning	-	-
Horse springer	No Hazard	-	-
Elephant springer	No Hazard	-	-

Comments :

Photo 1:



Photo 2:



Photo 3:





Authorised By:

Other

Immediate Action:

None

Inspection
Completed:

4 April 2023 at 10:19

Signature:

Addition
comments:

Location:



Townfield Lane Inspection Sheet



Inspection Start: 4 April 2023 at 10:29

Inspected By: Ian

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Cone climber	No Hazard	—	—
<hr/>			
Surface	No Hazard	—	—
<hr/>			
Signs	No Hazard	—	—
<hr/>			
Bin	No Hazard	—	—
<hr/>			
Hedges	No Hazard	—	—
<hr/>			
Seating	No Hazard	—	—
<hr/>			
Climbing Frame	No Hazard	—	—
<hr/>			
Free standing slide	No Hazard	—	—
<hr/>			

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Embankment slide	No Hazard	-	-
Steps	No Hazard	-	-
Embankment slide2	No Hazard	-	-
Trim trail	No Hazard	-	-
1 bay. 1 flat/1 cradle	No Hazard	-	-
2 bay 1 flat/1 cradle	No Hazard	-	-
2 bay basket	No Hazard	-	-
Play panel	No Hazard	-	-
Surface graphics	No Hazard	-	-

Comments :



Authorised By:

Ian

Immediate Action:

None

Inspection
Completed:

4 April 2023 at 10:31

Signature:

Addition
comments:

Location:



Cemetery Inspection Sheet




Inspection Start: 4 April 2023 at 11:09

Inspected By: Ian

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Paths	No Hazard	—	—
Trees	No Hazard	—	—
Hedges	No Hazard	—	—
Graves	No Hazard	—	—
Waste bin	All collected	—	—
Building	No Hazard	—	—
Grass areas	No Hazard	—	—

Comments :

A large, empty rectangular box with a thin black border, intended for entering comments. It occupies the upper right portion of the page.



Authorised By:

Ian

Immediate Action:

None

Inspection
Completed:

4 April 2023 at 11:09

Signature:

Addition
comments:

Location:



Ship Street Inspection/job sheet



Inspection Start: 28 March 2023 at 13:45

Inspected By: Steph

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Grass areas	—	—	—

Under construction Grass at the orchard could do with cutting

Hedges	—	—	—
--------	---	---	---

There's a bit on the hedge maybe needs a trim and the laurel bush needs topping

Trees	—	—	—
-------	---	---	---

Gate	—	—	—
------	---	---	---

Fence	—	—	—
-------	---	---	---

No lock on the double gate and the kid have got in

Bins x 3	All collected	None	Clean
----------	---------------	------	-------

X3 bins collected

All bins emptied on ship street

Task

Grass cut

Strimming

Spray

Comments :

All bins collected one missing top off bin

Photo 1:



Photo 2:



Photo 3:



Photo 4:



Photo 5:





Immediate Action:

None


Inspection
Completed:

5 January 2021 at 10:37

Signature:

Addition
comments:

Location:



War Memorial Inspection Sheet



Northwich
town council

Inspection Start: 28 March 2023 at 11:14

Inspected by: Kev

Equipment	Hazard	Risk H/M/L	Recommended Action/s
Car Park	—	—	—
A bit off a clean up			
Path	No Hazard	—	—
Could do with some soil and seed are turfing down the side of the path			
Trees	No Hazard	—	—
Some want a cut back			
Benches	—	—	—
Car park benches want painting could do with some more a long the pathway			
War Memorial	No Hazard	—	—
Moss treatment required			
Gate	No Hazard	—	—
Bins	No Hazard	—	—
Overflowing could do with some more bins along the path			

Comments:


A large, empty rectangular box with a thin black border, intended for writing comments. It occupies the upper right portion of the page.

Photo 1:



Photo 2:




Photo 3:



Photo 4:



Photo 5:



Photo 6:



Photo 7:



Photo 8:



Photo 9:



Photo 10:





Immediate Action:

None

Inspection
Completed:

Signature:

Addition
comments:

Location:

